

**GUIDELINES FOR ARCHITECTURAL PLANNING,
DESIGN, AND ROOM PROGRAMING (LP3A)**

**CENTER FOR COMMUNITY DEVELOPMENT
IN BAGAN, MYANMAR**

Compiled as a requirement
to obtain a Bachelor of Architecture degree



Written by:

Theingi Aung

NIM : 241003232010733

1st Supervisor:

Prof. Dr. Ars. Eko Nursanty, S.T., M.T.

NIDN: 0606046903

2nd Supervisor:

Djudjun Rusmiatmoko, S.T., M.Ars.

NIDN: 0602108106

**ARCHITECTURE STUDY PROGRAM
FACULTY OF ENGINEERING
UNIVERSITAS 17 AGUSTUS 1945 SEMARANG**

2025

PREFACE

Completing this Architectural Planning and Design Program Report, "*Center for Community Development in Bagan, Myanmar*," marks an important milestone in my academic journey toward a Bachelor's degree in Architecture at the Department of Architecture, Faculty of Engineering, University of 17 August 1945 Semarang.

I would like to express my deepest gratitude to all those who have contributed to the completion of this project:

1. Prof. Dr. Ars. Eko Nursanty, S.T., M.T., for your insightful mentorship, unwavering encouragement, and invaluable guidance throughout the process.
2. Mr. Djudjun Rusmiatmoko, S.T., M.Ars., for your continuous support, constructive feedback, and dedication to nurturing my academic growth.
3. All lecturers and staff of the Architecture Study Program, Faculty of Engineering, Universitas 17 Agustus 1945 Semarang — for your guidance, support, and shared expertise.
4. My beloved family and friends, for your endless patience, moral support, and belief in my abilities, without which this achievement would not have been possible.
5. The architects, scholars, and community members, whose dedication, creativity, and resilience have been an enduring source of inspiration throughout this work.

It is my sincere hope that the findings and recommendations offered in this report will contribute meaningfully to future academic studies and practical applications in the field of community-centered architectural design.



Semarang, 13 Januari 2024

Theingi Aung

NIM 241003232010733

STATEMENT PAGE

I, the undersigned:

Name: Theingi Aung
NIM: 241003232010733
Study Program: Architecture
Faculty: Engineering

hereby declare that the Final Project entitled "Center for Community Development in Bagan, Myanmar" is my own original work and is free from any form of plagiarism. All sources cited or referred to have been properly acknowledged according to the applicable academic standards. If, in the future, any evidence of plagiarism is found, I am willing to accept the sanctions in accordance with the relevant regulations.

I make this statement sincerely to be used as necessary.

Semarang, 13 Januari 2024



Theingi Aung

NIM 241003232010733

LIST OF CONTENTS

CHAPTER 1 INTRODUCTION**Error! Bookmark not defined.**

1.1 Background..... **Error! Bookmark not defined.**

1.2 Problem Statement . **Error! Bookmark not defined.**

1.3 Goals and Objectives**Error! Bookmark not defined.**

1.4 Benefits **Error! Bookmark not defined.**

1.5 Discussion Method. **Error! Bookmark not defined.**

1.6 Scope of Discussion**Error! Bookmark not defined.**

1.7 Discussion Systematics.....**Error! Bookmark not defined.**

1.8 Flow of Thought **Error! Bookmark not defined.**

CHAPTER 2 GENERAL OVERVIEW .**Error! Bookmark not defined.**

2.1 Definition of the title.....**Error! Bookmark not defined.**

2.1.1 Community Center..... Error! Bookmark not defined.

2.1.2 Bagan, City Error! Bookmark not defined.

2.1.3 Community Center in Bagan..... Error! Bookmark not defined.

2.2 Overview of the Community Centers **Error! Bookmark not defined.**

2.2.1 Types of Community Centers Error! Bookmark not defined.

2.2.2 Functions of Community Centers Error! Bookmark not defined.

2.2.3 Activities in Community Centers Error! Bookmark not defined.

2.2.4 Actors and Users in a Community Center..... Error! Bookmark not defined.

2.3 Key Principles of Community Center Design **Error! Bookmark not defined.**

CHAPTER 3 COMPARATIVE STUDY **Error! Bookmark not defined.**

3.1 Background..... **Error! Bookmark not defined.**

3.2 Introduction of The Community Development Center (CDC), by CCA.....**Error! Bookmark not defined.**

3.2.1 Overview of the CDC by CCA..... Error! Bookmark not defined.

3.2.2 Space Breakdown and floor area Estimation.. Error! Bookmark not defined.

3.2.3 Architectural Design..... Error! Bookmark not defined.

3.2.4 Functional Spaces Error! Bookmark not defined.

3.2.5 Materiality and Construction Error! Bookmark not defined.

3.2.6 Sustainability Features Error! Bookmark not defined.

3.2.7 Community Engagement..... Error! Bookmark not defined.

3.3 Introduction of Firstenburg Community Center
..... **Error! Bookmark not defined.**

3.3.1 Overview of Firstenburg Community Center.. Error! Bookmark not defined.

3.3.2 Space Breakdown and floor area Estimation.. Error! Bookmark not defined.

3.3.3 Architectural Design, Concept and Inspiration Error! Bookmark not defined.

3.3.4 Structure and Materials..... Error! Bookmark not defined.

3.3.5 Functional Interior Spaces..... Error! Bookmark not defined.

3.3.6 Site Ecology and Land Use..... Error! Bookmark not defined.

3.3.7 Day Light and Ventilation Error! Bookmark not defined.

3.3.8 Water Cycle of the building..... Error! Bookmark not defined.

3.3.9 Energy Flows of the project..... Error! Bookmark not defined.

3.4 Introduction of Bahan Community Center **Error! Bookmark not defined.**

3.4.1 General Description of Bahan Community Center..... Error! Bookmark not defined.

3.4.2 Space Breakdown and Floor Area Estimation Error! Bookmark not defined.

3.4.3 Activities in Community Center..... Error! Bookmark not defined.

3.4.4 Community Impact Error! Bookmark not defined.

3.4.5 Challenges and Considerations..... Error! Bookmark not defined.

3.5 Comparative Study Matrix.....**Error! Bookmark not defined.**

3.5.1 SWOT analysis of the three community centers Error! Bookmark not defined.

3.6 Insights for Proposed Community Center Design in Bagan **Error! Bookmark not defined.**

3.7 Conclusion of the Comparative Study **Error! Bookmark not defined.**

CHAPTER 4 SPECIAL REVIEW OF COMMUNITY CENTERS IN BAGAN **Error! Bookmark not defined.**

4.1 General Overview of the Old Bagan..... **Error! Bookmark not defined.**

4.1.1 Geographical Conditions of Bagan..... Error! Bookmark not defined.

4.1.2 Climate Conditions of Bagan Error! Bookmark not defined.

4.1.3 Spatial Planning Plan Error! Bookmark not defined.

4.1.4 Estimated Population Data for Bagan (2025). Error! Bookmark not defined.

4.1.5 Review of Spatial Planning Area in Bagan Error! Bookmark not defined.

4.1.6 Potential Planning Area..... Error! Bookmark not defined.

4.1.6.1 Nyaung-U Region **Error! Bookmark not defined.**

4.1.6.2 New Bagan **Error! Bookmark not defined.**

4.1.6.3 Potential Site Location in New Bagan Region**Error! Bookmark not defined.**

4.1.6.4 Data Summary for the Potential Planning Area **Error! Bookmark not defined.**

4.2 Special Review of Community Building Designs in Bagan **Error! Bookmark not defined.**

4.2.1 Definition of Community Building in Bagan.. Error! Bookmark not defined.

4.2.2 Key Characteristics of Community Buildings in BaganError! Bookmark not defined.

4.2.3 Significance of Community Buildings in Bagan Error! Bookmark not defined.

4.2.4 Activities and Functions of Community Buildings in Bagan..... Error! Bookmark not defined.

CHAPTER 5: CONCLUSION, LIMITATIONS, AND ASSUMPTIONS..... **Error! Bookmark not defined.**

5.1 Conclusion **Error! Bookmark not defined.**

5.2 Limitations **Error! Bookmark not defined.**

5.3 Assumptions..... **Error! Bookmark not defined.**

CHAPTER 6: APPROACH TO ARCHITECTURE PLANNING AND DESIGN.... **Error! Bookmark not defined.**

6.1 Planning Aspect Approach ...**Error! Bookmark not defined.**

6.1.1 Actor and Activity Approach Error! Bookmark not defined.

6.1.2 Actor Capacity Approach Error! Bookmark not defined.

6.1.2.1 Estimated Total Visitor for the Community Center **Error!**

Bookmark not defined.

6.1.2.2 Capacity Projection for the Next 10 Years **Error! Bookmark not defined.**

6.1.2.3 Operational Staff Estimation **Error! Bookmark not defined.**

6.1.3 Spatial Requirements Approach..... Error! Bookmark not defined.

6.1.4 Spatial Relationship Approach..... Error! Bookmark not defined.

6.1.5 Spatial Quantity Study Approach..... Error! Bookmark not defined.

6.2 Basic Design Approach.....**Error! Bookmark not defined.**

6.2.1 Functional Aspect Approach..... Error! Bookmark not defined.

6.2.2 Philosophical Aspect Approach..... Error! Bookmark not defined.

6.2.3 Technological Aspect Approach..... Error! Bookmark not defined.

6.2.4 Sustainable Aspect Approach..... Error! Bookmark not defined.

6.2.5 Interior and Exterior Spatial Layout Approach..... Error! Bookmark not defined.

6.2.5.1 Interior Spatial Approach: Layout, Comfort, and Material Adaptation to Design Needs **Error! Bookmark not defined.**

6.2.5.2 Exterior Spatial Approach: Landscaping and Outdoor Integration **Error! Bookmark not defined.**

6.3 Structural Systems Approach **Error! Bookmark not defined.**

6.3.1 Foundation Structure Approach *Error! Bookmark not defined.*

6.3.2 Column and Beam Structural Approach *Error! Bookmark not defined.*

6.3.3 Roof Structure Approach *Error! Bookmark not defined.*

6.4 Utility System Approach.....**Error! Bookmark not defined.**

6.4.1 Clean & Dirty Water Distribution System Approach.... *Error! Bookmark not defined.*

6.4.2 Natural and Artificial Lighting System Approach..... *Error! Bookmark not defined.*

6.4.3 Natural and Artificial Ventilation System Approach.... *Error! Bookmark not defined.*

6.4.4 Vertical Transportation System Approach *Error! Bookmark not defined.*

6.4.5 Fire Fighting System Approach *Error! Bookmark not defined.*

6.4.6 Lightning Protection System Approach *Error! Bookmark not defined.*

6.4.7 Security System Approach..... *Error! Bookmark not defined.*

6.4.8 Solid Waste Disposal System Approach *Error! Bookmark not defined.*

6.5 Site Selection Approach.....**Error! Bookmark not defined.**

6.5.1 Site Criteria..... *Error! Bookmark not defined.*

6.5.2 Site Selection..... *Error! Bookmark not defined.*

6.5.3 Site Criteria..... *Error! Bookmark not defined.*

6.5.4 Alternative Sites *Error! Bookmark not defined.*

6.5.4.1 Alternative Site 01 **Error! Bookmark not defined.**

6.5.4.2 Alternative Site 02 **Error! Bookmark not defined.**

6.5.4.3 Alternative Site 03 **Error! Bookmark not defined.**

6.5.5 Alternative Site Assessment..... *Error! Bookmark not defined.*

6.6 Conceptual Approach & Architectural Style. **Error! Bookmark not defined.**

6.6.1 Conceptual Framework..... *Error! Bookmark not defined.*

6.6.2 *Architectural Style* *Error! Bookmark not defined.*

CHAPTER 7 ARCHITECTURAL PLANNING AND DESIGN PROGRAM..... **Error! Bookmark not defined.**

7.1 Planning and Design Concepts ... **Error! Bookmark not defined.**

7.1.1 *Basis of the Design Approach* *Error! Bookmark not defined.*

7.1.2 *Purpose of the Design*..... *Error! Bookmark not defined.*

7.1.3 *Integration of Various Architectural Concepts**Error! Bookmark not defined.*

7.1.4 *Variety and Flexibility in Architectural Expression* *Error! Bookmark not defined.*

7.2 Space Program **Error! Bookmark not defined.**

7.3 Selected Site..... **Error! Bookmark not defined.**

7.3.1 *Local Planning and Zoning Regulations (Bagan Context)* *Error! Bookmark not defined.*

7.4 Building Structural System ...**Error! Bookmark not defined.**

7.4.1. *Foundation System* *Error! Bookmark not defined.*

7.4.2 *Structural Frame and Wall System* *Error! Bookmark not defined.*

7.4.3 *Structural Flexibility and Expansion*..... *Error! Bookmark not defined.*

7.5 Building Performance Systems... **Error! Bookmark not defined.**

7.5.1 *Utility Systems*..... *Error! Bookmark not defined.*

7.5.2 *Building Physics* *Error! Bookmark not defined.*

7.5.2.1 Interior Elements **Error! Bookmark not defined.**

7.5.2.2 Exterior Elements **Error! Bookmark not defined.**

REFERENCES **Error! Bookmark not defined.**

LIST OF FIGURES

- Figure 1** Figure 1 Minimum Floor Area for Various Activities.....Error! Bookmark not defined.
- Figure 2** Requirements for child care, Source: Matrix Handbook Planning-Design Data... Error! Bookmark not defined.
- Figure 3** Program Facilitators in Community Center,.....Error! Bookmark not defined.
- Figure 4** Diagram of Community Collaboration and External SupportError! Bookmark not defined.
- Figure 5** Wheelchair ramp of rise 650mm and Passing place for two wheelchairs..... Error! Bookmark not defined.
- Figure 6** Dimensions of adult female & male wheelchair usersError! Bookmark not defined.
- Figure 7** Elements of the plan of a community center.....Error! Bookmark not defined.
- Figure 8** Community Development Center (CDC) by CCAError! Bookmark not defined.
- Figure 9** The Interior Garden of CCA.....Error! Bookmark not defined.
- Figure 10** Floor Layout Plan of CDC, Source: ArchDailyError! Bookmark not defined.
- Figure 11** Sections & Elevations of CDC, Source: ArchDailyError! Bookmark not defined.
- Figure 12** Exterior Material of (CDC) by CCA.....Error! Bookmark not defined.
- Figure 13** A community activity taken at CDC, Source: cca.mxError! Bookmark not defined.
- Figure 14** Firstenberg Community Center, Source: In situ architecture.....Error! Bookmark not defined.
- Figure 15** Firstenberg Community Center, Source: In situ architecture.....Error! Bookmark not defined.
- Figure 16** Exterior Material images of Firstenberg Community CenterError! Bookmark not defined.
- Figure 17** Floor Plans of the Furstenberg Community CenterError! Bookmark not defined.
- Figure 18** Interior spaces of Firstenberg Community CenterError! Bookmark not defined.
- Figure 19** Interior spaces of Firstenberg Community CenterError! Bookmark not defined.
- Figure 20** Site Features and sun path diagram.....Error! Bookmark not defined.
- Figure 21** Day Light and Ventilation Features.....Error! Bookmark not defined.
- Figure 16 & 22** Water Use Reduction Graph.....Error! Bookmark not defined.
- Figure 23** Mechanical Air Handler Systems.....Error! Bookmark not defined.
- Figure 24** Exterior Perspective of Bahan Community CenterError! Bookmark not defined.
- Figure 25** Bahan Community center opening ceremony.....Error! Bookmark not defined.
- Figure 26** Community fever clinic in Bahan community centerError! Bookmark not defined.
- Figure 27** Map of Bahan Township, Yangon Region, MyanmarError! Bookmark not defined.
- Figure 28** Renderings of Bahan Community Center.....Error! Bookmark not defined.
- Figure 29** Bagan Skyline.....Error! Bookmark not defined.
- Figure 30** Occurrence of wet and dry spells of rainfall in Bagan, MyanmarError! Bookmark not defined.
- Figure 31** Location of 27 sacred compounds (survey sites) within Monumental Zone 1 (MZ-1) of the Bagan Cultural Heritage Site.....Error! Bookmark not defined.
- Figure 32** Maps Showcasing Old Bagan, New Bagan and Nyaung-U region..... Error! Bookmark not defined.
- Figure 33** Maps of Nyaung-U RegionError! Bookmark not defined.
- Figure 34** Potential Site Locations & Icons near the Site.....Error! Bookmark not defined.
- Figure 35** Bagan district public library,Error! Bookmark not defined.
- Figure 36** Local Artisans working in lacquerware workshopsError! Bookmark not defined.
- Figure 37** Image of Nat Taung Kyaung Monastery, Bagan, Myanmar.....Error! Bookmark not defined.
- Figure 38** Burmese Traditional Architecture Ornaments of Nat Taung Kyaung Monastery Error! Bookmark not defined.
- Figure 39** (3D) Massing Models of Shin-Bo-Me-Ok-Kyaung Monastery,.....Error! Bookmark not defined.

Figure 40 Sanon Training Restaurant & Bar.....Error! Bookmark not defined.

Figure 41 Burmese String Puppet Show(Yoke The'),Error! Bookmark not defined.

Figure 42 Bar Graph of Myanmar's Tourist Arrivals: Mandalay & Bagan.....Error! Bookmark not defined.

Figure 43 Analysis of Spatial Zones in Bagan Community Center, Source: Author's Analysis Error! Bookmark not defined.

Figure 44 Schematic Diagram of Spatial Connections between.....Error! Bookmark not defined.

Figure 45 Schematic Diagram of Spatial Connections between.....Error! Bookmark not defined.

Figure 46 Schematic Diagram of Complementary Facilities,Error! Bookmark not defined.

Figure 47 Estimated Area Percentage Pie Chart, Author's AnalysisError! Bookmark not defined.

Figure 48 Courtyards and paths found at Bagan TemplesError! Bookmark not defined.

Figure 49 Stages in Bored-Pile Foundation,Error! Bookmark not defined.

Figure 50 Seismic retrofit strategies for moment-resisting frames:Error! Bookmark not defined.

Figure 51 Common Beam Types: Essential Structural Elements in Construction,..... Error! Bookmark not defined.

Figure 52 Section plan of double-skin ventilation roof for building,.....Error! Bookmark not defined.

Figure 53 Schematic illustration of a traditional teak farmhouse,Error! Bookmark not defined.

Figure 54 Implement Filtration & First-Flush Diversion for Purity,.....Error! Bookmark not defined.

Figure 55 A Jali brick wall at The Reading Room ventilates & softens.....Error! Bookmark not defined.

Figure 56 Interior view of a Bagan temple,Error! Bookmark not defined.

Figure 57 Different types of artificial Lightings use in Architecture, Source: Arch Daily ... Error! Bookmark not defined.

Figure 58 Reference Outdoor architectural lighting in Westquay Shopping Centre in Southampton, Error! Bookmark not defined.

Figure 59 Natural Ventilation Illustrations, Source: 07 sketchesError! Bookmark not defined.

Figure 60 Mechanical Ventilations Solutions Diagrams, Source: thegreenage.co.uk..... Error! Bookmark not defined.

Figure 61 IoT-Powered Smart Fire Evacuation & Control System with Hybrid AI,..... Error! Bookmark not defined.

Figure 62 Cable system – Conventional lighting protection,Error! Bookmark not defined.

Figure 63 High Efficiency solar powered video surveillance camera,Error! Bookmark not defined.

Figure 64 A variety of colors and styles of waste disposal units and recycling bins, Error! Bookmark not defined.

Figure 65 Community workshops on waste reduction & Composting,.....Error! Bookmark not defined.

Figure 66 Site Option 01.....Error! Bookmark not defined.

Figure 67 Alternative Site 02.....Error! Bookmark not defined.

Figure 68 Alternative Site 03.....Error! Bookmark not defined.

Figure 69 Reference Images of Magyizin-Hospital-Myanmar ,showcasing material language,..... Error! Bookmark not defined.

Figure 70 Reference Images of Magyizin-Hospital-Myanmar,.....Error! Bookmark not defined.

Figure 71 Selected Site LocationError! Bookmark not defined.

Figure 72 Ventilation clay brick walls at a Costa Rica community center,.....Error! Bookmark not defined.

Figure 73 Reference Roofing system at a Costa Rica community center,Error! Bookmark not defined.

LIST OF TABLES

Table 1 Flow of Thought	Error! Bookmark not defined.
Table 2 Estimated Visitors of CDC by CCA	Error! Bookmark not defined.
Table 3 Space Breakdown and floor area Estimation of CDC by CCA	Error! Bookmark not defined.
Table 4 Estimated Visitors of Firstenberg Community Center	Error! Bookmark not defined.
Table 5 Space Breakdown and floor area Estimation of Firstenberg Community Center...	Error! Bookmark not defined.
Table 6 Estimated Visitors of Bahan Community Center, Author's Analysis ...	Error! Bookmark not defined.
Table 7 Space Breakdown and Floor Area Estimation of Bahan Community Center ...	Error! Bookmark not defined.
Table 8 Comparative Study Matrix of Case Studies	Error! Bookmark not defined.
Table 9 SWOT analysis of the three community centers	Error! Bookmark not defined.
Table 10 Estimated Population Data for Bagan (2025)	Error! Bookmark not defined.
Table 11 The tourism data of Bagan , Author's Analysis	Error! Bookmark not defined.
Table 12 Review of Spatial Planning Area in Bagan	Error! Bookmark not defined.
Table 13 Map of New Bagan, Source: Google Maps	Error! Bookmark not defined.
Table 14 Data Summary for the Potential Planning Area in Bagan	Error! Bookmark not defined.
Table 15 Analysis of Actors & Activities	Error! Bookmark not defined.
Table 16 Bagan Population Census and Tourist Arrivals Data	Error! Bookmark not defined.
Table 17 Estimated Community Center Visitors	Error! Bookmark not defined.
Table 18: Visitor Projection Table for the next 10-Year	Error! Bookmark not defined.
Table 19 Estimated Operational Staff Estimation, Source: Author's Analysis .	Error! Bookmark not defined.
Table 20 Analysis of the spatial requirements based on Actors and Activities, Author's Analysis	Error! Bookmark not defined.
Table 21 Reference Sources of Spatial Quantities	Error! Bookmark not defined.
Table 22 Estimated Space Requirements for Cultural Activity Areas, Author's Analysis ..	Error! Bookmark not defined.
Table 23 Estimated Space Requirements for Educational & Art Activity Spaces, Author's Analysis .	Error! Bookmark not defined.
Table 24 Estimated Space Requirements for Sports, Recreational & Communal Spaces,...	Error! Bookmark not defined.
Table 25 Estimated Space Requirements for Complementary Activity Spaces, Author's Analysis	Error! Bookmark not defined.
Table 26 Estimated Space Requirements for Service, Admin, Security	Error! Bookmark not defined.
Table 27 Estimated Space Requirements for Outdoor Activity Spaces, Source: Author's Analysis	Error! Bookmark not defined.
Table 28 Estimated Parking Area & Capacity, Source: Author's Analysis	Error! Bookmark not defined.
Table 29 Interior Spatial Elements and Their Role in Comfort and Cultural Adaptation ..	Error! Bookmark not defined.
Table 30 Native Tree Species with Cultural and Ecological Significance	Error! Bookmark not defined.
Table 31 Drought-Tolerant Shrubs with Cultural and Ecological Significance Error!	Error! Bookmark not defined.
Table 32 Artificial Lighting Strategies for Different Spaces in a Community Center	Error! Bookmark not defined.
Table 33 Site Criteria Analysis Table	Error! Bookmark not defined.
Table 34 Alternative Site Assessment Table	Error! Bookmark not defined.
Table 35 Estimated Overall Area, Source: Author's Analysis	Error! Bookmark not defined.

Table 36 Roofing Material Specifications and DescriptionsError! Bookmark not defined.

Abstract

Bagan, a UNESCO World Heritage Site in Myanmar, faces pressing socio-economic challenges despite its cultural significance and growing tourism sector. This thesis proposes a **Center for Community Development** that addresses local needs for education, vocational training, social welfare, and cultural preservation, while respecting the architectural identity of Bagan. The design integrates traditional Burmese aesthetics with sustainable, multifunctional spaces to empower local communities and enhance resilience. Through comparative analysis of global precedents and a context-sensitive design approach, the project aims to bridge the gap between heritage conservation and modern community development, offering a replicable model for culturally rooted, socially inclusive architecture in heritage-rich regions.